

09/695,604

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,731,098 B1
DATED : May 4, 2004
INVENTOR(S) : Hintz et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1.


Line 11, "alternator particular" should be -- alternator. In particular --.

Column 8.

Line 62, "port and" should be -- port 501 and --.

Signed and Sealed this

First Day of February, 2005



JON W. DUDAS
Director of the United States Patent and Trademark Office